

Lot-1916

875 Versatile

Joe's Repair LLC

11816 N. Champlin RD.

Billings, OK 74630

Date	Invoice #
10/2/2023	3865

Phone #	5807253417
---------	------------

PAID
10/02/2023

Bill To	Ship To
Bobbit	Bobbit

FARM TAX EXEMPT #	Rep	terms	P.O. No.	S O no	model
		Due on receipt		1845	

Item	Description	Orde...	Prev. In...	Back...	Invoic...	U/M	Rate	location	Amount
labor	875 versatile air conditioner not working all the time. replace the wiring from the compressor to the high pressure switch. park brake. hook up and adjust. tighten all belts, replace the alternator, alternator belts, and the pulley. Change the crankshaft pulley. will not start from in the cab . FIX THIS FIRST!!!!!!! Found the wire broken off at the ground relay.	8.5	0		8.5		110.00		935.00
30343571n	alternator	1	0	0	1		436.21		436.21T
3064230	pulley	1	0	0	1		298.40		298.40T
3036052	adaptor	1	0	0	1		159.99		159.99T
213326	pulley	1	0	0	1		118.43		118.43T
00057262	belt set	1	0	0	1		17.14		17.14T
1397	belt dressing	1	0	0	1		10.66		10.66T
MISCELL...	wire, wire ends, plastic ties, nuts bolts and washers.	1	0	0	1		25.00		25.00T

air conditioner - back emergency pulleys starter

belts + pulleys

We had all the brake parts

Thank you for your business.	Subtotal	\$2,000.83
<p>unless otherwise provided by law. The seller (above named dealership) Herby expressly disclaims all warranty of merchant-ability or fitness for A particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.</p> <p>\$2000.83</p>	Sales Tax (0.0%)	\$0.00
	Total	\$2,000.83
	Payments/Credits	-\$2,000.83
	Balance Due	\$0.00